baby&child
RESTORATION HARDWARE

WYLER QUEEN BED

PARTS INCLUDED

A [1] HEADBOARD
B [2] SIDE RAILS
C [1] FOOTBOARD
D [13] BED SLATS
E [2] SUPPORT SLAT

NO.	ITEM	DESCRIPTION	QTY.
1		Threaded Rod	8 pcs.
2		Curved Washer	8 pcs.
3		Lock Washer	8 pcs.
4		Hex Nut	8 pcs.
5		Wrench	1 pc.

ASSEMBLY INSTRUCTIONS

1. Place the headboard (A) upright in the position you wish the bed to be in when fully assembled.
2. Secure the threaded rod (1) to the fixed nut in the headboard (A) by simply turning it manually.
3. Raise the side rail (B) up and place the rod (1) to align with the bore holes on the end of the side rail (B). Put the side rail (B) up against the headboard (A) so the threaded rods (1) go through the bore holes. Insert curved washer (2), lock washer (3) and place hex nuts (4) on threaded rod (1) then tighten the hex nuts (4) with wrench (5), as illustrated in FIGURE 1.
4. Repeat the above procedure with the other side rail (B) to attach it to the headboard (A), and then repeat to connect side rails (B) to the footboard (C).
5. On inside of both headboard (A) and footboard (C) are pre-installed wooden brackets for the support slat (E). Set the support slat (E) on the wood bracket, as illustrated in FIGURE 2.
6. On inside surface of both side rails (B) are cavities designed to hold the individual bed slats (D). Set individual bed slats (D) on both sides of the side rails (B) as illustrated in FIGURE 3.
7. Assembly is complete.

FIGURE 1



FIGURE 2



FIGURE 3



baby&child
RESTORATION HARDWARE

WYLER QUEEN BED



CARE INSTRUCTIONS

1. Dust often using a clean, soft, dry and lint-free cloth.
2. Blot spills immediately and wipe with a clean, damp, cloth.
3. We do not recommend the use of chemical cleansers, abrasives or furniture polish on our lacquered finish.

IMPORTANT SAFETY INSTRUCTIONS

1. Please read all instructions carefully before assembling.
2. For your safety, assembly by two or more adults is strongly recommended.
3. Keep instructions for future use.
4. Use only vendor supplied hardware to assemble. Using unauthorized hardware could jeopardize the structural integrity of the item.